This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.



TITLE: Electroporation-Mediated Introvascular Delivery SN: 10/020,531 BLG: GTI-1180-CON1






FIG. 1



Before autofluoresciencecorrection (2 hrs. after excision)





Non-pulsed artery

FIG. 2B

Before autofluoresciencecorrection (2 hrs. after excision)





R1L1: Heparin, no pulse (left artery) 8hrs.

FIG. 3A




R2L1: Heparin, with pulse (left artery) 5hrs.

FIG. 3C



R1R1: Heparin, with pulse (right artery) 8hrs.


FIG. 3B



R2R1: Heparin, no pulse (right artery) 5hrs.

FIG. 3D







4L2: Heparin, with pulse (left artery) FIG. 4A




4R2: Heparin, no pulse (right artery) FIG. 4B



4L1: Heparin, with pulse (left artery) FIG. 4C



1L3: Heparin, no pulse (left artery) FIG. 4D







12R1: Heparin, with pulse (right artery) FIG. 5A



12L1: Heparin, no pulse (left artery) FIG. 5B

Title: Electroporation-Mediated Introvascular Delivery

SN: 10/020,531 BLG: GTI-1180-CON1







FIG. 6

Title: Electroporation-Mediated Introvascular Delivery SN: 10/020,531 BLG: GTI-1180-CON1










FIG. 8A






FIG. 8B




FIG. 8C